

KEY TO THE INSPECTION REPORT

Report #: 122705-1

This Report lists the systems and components inspected by this company. Items not found in this report are considered beyond the scope of this inspection, and should not be considered inspected at this time.

"APPEAR SERVICEABLE" means that we did not observe conditions that would lead us to believe problems existed with this system or component. The item is capable of being used. Some serviceable items may, however, show wear and tear. Other conditions if applicable, will be noted in the body of the report.

Significantly deficient systems or components will be identified as: Not functional / unsafe / worn / near end of lifespan. When in the inspector's opinion, an item is "significantly deficient", the reason will be within the body of the report.

Please read the entire report for all items .

Notice: This report contains technical information that may not be readily understandable to the lay person. Therefore, a verbal consultation with the inspector is a mandatory part of this inspection report. If you choose not to consult with the inspector, this inspection company cannot be held liable for your understanding or misunderstanding of this report's contents. If you were not present during this inspection please call the office to arrange for your verbal consultation.

KEY TO THE INSPECTION REPORT

* Items that have an asterisk next to them. This item or component warrants additional attention, repair or monitoring.

(1) Items that have a (1) next to them. The Bracketed Numbers are defined as follows:

- (1) Recommended evaluation by a qualified licensed structural engineer / geotechnical engineer.
(2) Recommend further review and repairs as needed by a qualified licensed contractor or specialty tradesman dealing with that item or system.
(3) Recommend further review for the presence of any wood destroying pests or organisms by qualified Pest Inspector.
(4) This item is a safety hazard - correction is needed
(5) Recommend upgrading for safety enhancement. This building may have been constructed before current safety standards were developed.

If you do not understand how to read this report please contact our office.

I have read and understand the Key to the Matrix Inspection Report.

Client's Initials Representative/Agent's Initials

I agree to read the special "NOTICES" in each section of the report for further information concerning the limitations of this inspection.

Client's Initials Representative/Agent's Initials

Present During The Inspection: Client Buyer's Agent Seller's Agent Seller

INSPECTOR : Gary T. Clark Inspector

Inspection Date: Dec/27/2005, Tuesday

Start Time: 8:00 am

Completion Time: 11:30 am

The weather condition at the time of inspection was Dry

Approximate temperature during inspection 45.0

Property Information:

The subject property inspected was a (an): Single Family. # of units 1
Approximate age of building: 2003 Stated by: MLS Listing
Approximate age of roof: 2003 Stated by: Inspector
Additions / Alterations to: Stated by:

NOTICE: It is always wise to check with the building department for permit information, especially if additions or alterations are noted.

IMPORTANT NOTICE TO THIRD PARTIES OR OTHER PURCHASERS: RECEIPT OF THIS REPORT BY ANY PURCHASERS OF THIS PROPERTY OTHER THAN THE PARTY(IES) IDENTIFIED ON THE CONTRACT PAGE #1 IS NOT AUTHORIZED BY THE INSPECTOR. THE INSPECTOR STRONGLY ADVISES AGAINST ANY RELIANCE ON THIS REPORT. WE RECOMMEND THAT YOU RETAIN A QUALIFIED PROFESSIONAL INSPECTOR TO PROVIDE YOU WITH YOUR OWN INSPECTION AND REPORT ON THIS PROPERTY.